

HARTZELL INC  
INSPECT

Part Number: C300070

Date: 6/10/2010

Work Order #: M138070

PHC-C3YF-2UF/FC7693DFB

Hydr Unit No. NA		Bulkhead No. NA		Valve No. NA						
00961	Blade 2: L00962	Blade 3: L00963	Blade 4:	Blade 5:	Blade 6:					
	Clamp 2:	Clamp 3:	Clamp 4:	Clamp 5:						
Start Lock NA	Low Pitch 13.0	High Pitch 18.0	Feather 81.1	Position	Orient	Qty/Al	St	Scrw	A-2424-1	Washer
Radius (inches) for angles: 30				1	L	0	0	0	0	1
				3	L	0	0	2	0	0
Comments: Access Kit: 5E2748-1      Included but not inst.										
Packing Certified By: <i>TJM</i>				Date: 6-10-10						
Inspected By: Tim Jess										

The approved design data for this propeller incorporates all changes required by applicable Airworthiness Directives.

J A AIR CENTER AURORA AIRPORT/SUGAR GROVE, IL 60554 P 1  
 Repair Station #NF2R029L PROPELLER LOG #2  
 Type CESSNA 340A TT -0-  
 N # 34089 TSMOH  
 S/N 340A0371 REC. HR. METER 2543  
 PROPELLER MODEL PHC-C3YF-2UF/FC7693DFB  
 PROPELLER S/N EB7284B

RH PROPELLER INSTALLATION-  
 INSTALLED THIS PHC-C3YF-2UF/7693DF S/N EB7284B ON 340A0371  
 AS PER STD SA09971SC-D INSTALLATION OF HARTZELL MODEL PHC-  
 C3YF-2UF/7693DF PROPELLERS IN ACCORDANCE WITH RAM DRAWING  
 NO. 2549 INITIAL RELEASE, DATED MAY 16, 2001 OR LATER FAA  
 APPROVED REVISION. FAA APPROVED RAM AIRPLANE FLIGHT MANUAL  
 SUPPLEMENT AFMS 1696, INITIAL RELEASE DATED MAY 16, 2002 OR  
 LATER FAA APPROVED REVISION IS REQUIRED.  
 THE AIRCRAFT, ENGINE, APPLIANCE, OR COMPONENT IDENTIFIED WAS  
 REPAIRED & INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS  
 OF THE FEDERAL AVIATION AGENCY AND IS APPROVED FOR RETURN TO  
 SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS  
 REPAIR STATION UNDER W.O. # 18702 DATE: APRIL 7, 2011  
 SIGNED: BRUCE P. REBECHINI *Bruce P. Rebechini* For  
 J.A. AIR CENTER, AURORA AIRPORT, SUGAR GROVE, IL 60554  
 F.A.A. APPROVED REPAIR STATION #NF2R029L

**RH PROP SINCE NEW**

SUB-TOTALS this page

TOTALS—Carry forward to next page